

**Report Date** 1/1/2008

**Company** Quality Home Inspection  
**Address** 416-723-8913  
**Thermographer** Igor Krylov

**Customer** John Doe  
**Site Address** 5 Main St., Toronto, ON  
**Contact Person** John Doe




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2008:02:01 21:47:48	
Image Name	IR_0048.jpg	
Emissivity	0.95	
Reflected Temperature	22.0 °C	
Object Distance	6.6 ft	

**Description**

There is an insulation problem in the corner of the leaving room. There is an air infiltration into the house. Problem: heat lost, moisture build up, growing mold in the future. Problem needs further investigation and correction.

**Report Date** 1/1/2008

**Company** Quality Home Inspection

**Address** 416-723-8913

**Thermographer** Igor Krylov

**Customer** John Doe

**Site Address** 5 Main St., Toronto, ON

**Contact Person** John Doe




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2008:02:29 22:09:36	
Image Name	IR_0078.jpg	
Emissivity	0.95	
Reflected Temperature	22.0 °C	
Object Distance	6.6 ft	

**Description**

There is an air draft around the window in the bedroom. Problem: heat lost, moisture build up, overpayment for heating and cooling. Problem needs to be corrected.

**Report Date** 1/1/2008

**Company** Quality Home Inspection  
**Address** 416-723-8913  
**Thermographer** Igor Krylov

**Customer** John Doe  
**Site Address** 5 Main St., Toronto, ON  
**Contact Person** John Doe




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2008:02:29 23:05:12	
Image Name	IR_0100.jpg	
Emissivity	0.95	
Reflected Temperature	22.0 °C	
Object Distance	6.6 ft	

Description
<p>There is a poor or missing insulation in the arc above bed in the master bedroom. Problem: heat lost, moisture build up, growing mold in the future. Problem needs further investigation and correction.</p>

**Report Date** 1/1/2008

**Company** Quality Home Inspection  
**Address** 416-723-8913  
**Thermographer** Igor Krylov

**Customer** John Doe  
**Site Address** 5 Main St., Toronto, ON  
**Contact Person** John Doe




Image and Object Parameters		Text Comments
Camera Model	FLIR B-CAM Western S	
Image Date	2008:02:29 23:20:47	
Image Name	IR_0103.jpg	
Emissivity	0.95	
Reflected Temperature	22.0 °C	
Object Distance	6.6 ft	

**Description**

There is an electrical problem. Overheat breaker. Problem needs to be checked and fixed by professional electrician.